



VEHICLE INSPECTION REPORT

KY11OBF

Mazda 6 2.0 Takuya 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	01/03/2011	Keys	2	CAP Clean	£920.00
Year	2011	Service history	Yes	CAP Average	£530.00
Mileage	159,158 Miles Warranted	Service documents	Printout	CAP Below	£250.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	RED	Last service date	22/07/2024	Gears	6
VIN	JMZGHA4E601426634	Last service miles	145,750	Doors	5
Body Style	Hatchback	MOT Due	18/12/2025		

£100 ADDITIONAL FEE. Last Service: 22/07/2024 at 145750 miles. (3 services) Front lights cloudy
Power steering fault


Tyres		
NSF	SUNNY	3.0mm
NSR	UNIROYAL	2.0mm
OSF	UNIROYAL	2.0mm
OSR	UNIROYAL	3.0mm
Spare		

Features


- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Audio remote control
- Towbar
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Boot Lid
Scratched
Over 25mm Not Thru Paint




2: Bumper Rear
Scratched
Over 100mm Thru Paint



3: Wheel osr
Scratched
Over 50mm



4: Qtr Panel osr
Chipped
1 To 5



5: Door osr
Dented
Over 30mm



6: Door osf
Chipped
1 To 5



7: Wing osf
Chipped
Multiple Chips



8: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image

9: Bumper Front
Scratched
Over 25mm Not Thru Paint



10: Bonnet
Chipped
1 To 5



11: Wheel nsf
Scratched
Over 50mm

No Image

12: Wing nsf
Scratched
Over 25mm Not Thru Paint



13: Door nsf
Dented
Over 2 UpTo 10mm



14: Door nsr
Chipped
1 To 5




15: Qtr Panel nsr
Poor Previous Repair
Poor Paint



16: Wheel nsr
Scratched
Over 50mm



17: Roof
Dented
Between 10mm + 30mm



18: Seat Back Cover osf
Torn
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	Fault