



# VEHICLE INSPECTION REPORT

**LD63AEK**

## Nissan Qashqai 1.6 [117] 360 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	31/10/2013	Body Style	Hatchback	Last service miles	127,142
Year	2013	Keys	2	MOT Due	30/10/2026
Mileage	127,601 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	WHITE	Number of stamps	1	Doors	5
VIN	SJNFAAJ10U2877847	Last service date	18/05/2026		

£90 ADDITIONAL FEE

Last service 18/05/2026 at 127,142 miles- 1 service Glass roof cracked

### Tyres

NSF	GT RADIAL	3.0mm
NSR	GT RADIAL	5.0mm
OSF	GT RADIAL	5.0mm
OSR	GT RADIAL	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Digital radio
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Park assist camera
- Radio/CD
- Front fog lights
- Front armrest
- Rear electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Insecure  
Action Required



3: Bumper Front  
Poor Previous Repair  
Poor Paint



4: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



5: Wheel nsf  
Scratched  
Over 50mm



6: Wing nsf  
Scratched  
Up To 25mm Thru Paint



7: Door nsf  
Chipped  
Edge Chip



8: Door nsr  
Dented  
Between 10mm + 30mm



9: Door nsr  
Chipped  
Edge Chip



10: Wheel nsr  
Scratched  
Over 50mm



11: Glass Roof  
Cracked  
Replace



12: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



13: Bumper Rear Moulding  
Scuffed (Unpainted)  
UpTo 100mm



14: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



15: Wheel osr  
Scratched  
Over 50mm



16: Door osr  
Dented  
Between 10mm + 30mm



17: Door osf  
Scratched  
UpTo 25mm Thru Paint



18: Door osf  
Dented  
2 Or Less UpTo 10mm



19: Wheel osf  
Scratched  
Over 50mm

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK