



VEHICLE INSPECTION REPORT

GV14XBD

Volkswagen Golf 2.0 TDI GT 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	21/07/2014	Body Style	Hatchback	Last service miles	81,580
Year	2014	Keys	2	MOT Due	22/10/2026
Mileage	85,113 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	7	Doors	5
VIN	WVWZZZAUZEP080267	Last service date	01/07/2025		

£90 ADDITIONAL FEE

Cambelt replaced 29/08/2019 at 45,613 miles

Last service 01/07/2025 at 81,580 miles- 7 services (3 main dealer) Service due message displayed

Eml light is on

Car been plugged in and detected:

Cylinder 2 glow plug circuit

Tyres


NSF	MICHELIN	4.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Back Cover of
Torn
Over 3mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Poor Previous Repair
Paint Flake



4: Wing osf
Poor Previous Repair
Poor Paint



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



9: B Post ns
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Sill ns
Scratched
Over 25mm Thru Paint



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Bumper Rear
Cracked
Over 25mm




15: Other
N/A
N/A



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Scratched
Over 25mm Thru Paint



19: Door osf
Dented
Over 30mm




20: Sill os
Scratched
Over 25mm Thru Paint



21: Other
N/A
N/A



22: Wheel osf
Scratched
Up To 50mm



23: Screen Front
Chipped
Up To 10mm



24: A Post os
Chipped
1 To 5



25: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK