



VEHICLE INSPECTION REPORT

NX59UMO

Ford Fusion 1.4 Zetec 5dr [Climate]

nama
 GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	01/09/2009	Body Style	Hatchback	Last service miles	55,759
Year	2009	Keys	2	MOT Due	29/06/2026
Mileage	69,227 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	11	Doors	5
VIN	WFOUXXGAJU9M82854	Last service date	21/06/2021		

£100 ADDITIONAL FEE

Last service 21/06/2021 at 55,759 miles- 11 services (2 main dealer)
 Driver side rear door open message displayed constantly

Tyres

NSF	FALKEN	5.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	TRIANGLE	6.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Remote central locking
- Rear wiper
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Cloth seat trim
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Broken
Replace



6: A Post ns
Scratched
Over 25mm Thru Paint



7: Wing Front Arch Extension ns
Broken
Replace



8: Other
N/A
N/A



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Tailgate
Dented
With Paint Damage



14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: C Post ns
Dented
Between 10mm + 30mm



16: Bumper Rear
Scratched
Over 100mm Thru Paint



17: Other
N/A
N/A



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Wheel osr
Scratched
Over 50mm




20: Door osr
Dented
Between 10mm + 30mm



21: Door osr
Scratched
Over 25mm Thru Paint



22: Door osf
Chipped
Edge Chip



23: Door osf
Scratched
Over 25mm Thru Paint



24: Wing osf
Scratched
Over 25mm Thru Paint



25: Wheel osf
Scratched
Over 50mm



26: Screen Front
Scratched
Over 30mm



27: Bonnet
Dented
Between 10mm + 30mm



28: Front TowEye Cvr
Missing
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK