



VEHICLE INSPECTION REPORT

FA15AZC

Nissan Qashqai 1.5 dCi [110] Acenta 5dr

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |

nama
GRADE
5

Details

| | | | | | |
|-----------|----------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 14/07/2015 | Body Style | Hatchback | Last service miles | 123,693 |
| Year | 2015 | Keys | 2 | MOT Due | 17/08/2026 |
| Mileage | 146,078 Miles Warranted | Service history | Yes | Gearbox | MANUAL |
| Fuel Type | Diesel | Service documents | Service Book | Gears | 6 |
| Colour | GREY | Number of stamps | 8 | Doors | 5 |
| VIN | SJNFAAJ11U1364388 | Last service date | 15/08/2024 | | |

Last service 15/08/2024 at 123,693 miles- 8 services (2 main dealer)

Tyres


| | | |
|-------|--------------|-------|
| NSF | WESTLAKE | 3.0mm |
| NSR | COOPER TIRES | 5.0mm |
| OSF | WESTLAKE | 5.0mm |
| OSR | AUTOGREEN | 5.0mm |
| Spare | | |

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: B Post os
Dented
Over 30mm



2: Bonnet
Dented
Between 10mm + 30mm



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Bumper Front
Chipped
Multiple Chips



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Dented
Over 30mm



8: Aperture Seal nsf
Broken
Replace



9: Door nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel osr
Dented
With Paint Damage



12: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



13: Bumper Rear
Insecure
Action Required



14: Bumper Rear
Scratched
25 to 100mm Thru Paint



15: Qtr Panel osr
Dented
Between 10mm + 30mm



16: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



17: Door osr
Dented
Over 30mm



18: Door osf
Dented
Over 30mm



19: Wing osf
Dented
Over 30mm



20: Wheel osf
Scratched
Over 50mm



21: Roof
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |