



VEHICLE INSPECTION REPORT

BX16HDN

Vauxhall Meriva 1.4T 16V SE 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	01/03/2016	Body Style	MPV	Last service miles	40,893
Year	2016	Keys	2	MOT Due	16/04/2027
Mileage	40,909 Miles Not Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BROWN	Number of stamps	9		
VIN	W0LSH9EM4G4141866	Last service date	08/04/2026		

Last service 08/04/2026 at 40,893 miles- 9 services (5 main dealer) Mileage not correct

Tyres

NSF	LAUFENN	5.0mm
NSR	NEXEN	4.0mm
OSF	LAUFENN	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Climate control
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Traction control
- Alloy wheels
- PAS
- Trip computer
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Alarm

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Up To 50mm



5: Door nsf
Chipped
1 To 5



6: Door nsr
Dented
2 Or Less Up To 10mm



7: Qtr Panel nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel osr
Dented
Between 10mm + 30mm



10: Wheel osr
Scratched
Over 50mm



11: Door osr
Poor Previous Repair
Poor Paint



12: Door osf
Dented
Over 30mm



13: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		