



VEHICLE INSPECTION REPORT

GV65KHW

Mercedes-Benz GLA GLA 220d 4Matic AMG Line 5dr Auto [Premium]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	08/01/2016	Body Style	Estate	Last service miles	50,389
Year	2016	Keys	2	MOT Due	28/01/2027
Mileage	50,778 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	9		
VIN	WDC1569052J219296	Last service date	02/04/2026		

Last service 02/04/2026 at 50,389 miles- 9 main dealer services Engine misfires , Starter motor faulty

Tyres

NSF	NEXEN	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	NEXEN	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsf
Chipped
1 To 5



7: Door nsr
Scratched
UpTo 25mm Thru Paint



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Chipped
1 To 5



11: Wheel osr
Scratched
Over 50mm



12: Door osf
Chipped
Edge Chip



13: Wheel osf
Scratched
Over 50mm



14: Door osr
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK