



# VEHICLE INSPECTION REPORT

**GX63NVC**

## Vauxhall Astra 1.7 CDTi 16V ecoFLEX Energy 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**5**

### Details

Reg. date	02/09/2013	Body Style	Hatchback	Last service miles	53,438
Year	2013	Keys	2	MOT Due	30/03/2027
Mileage	108,916 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	10	Doors	5
VIN	W0LPC6EK1D1094472	Last service date	29/03/2022		

Last service 29/03/2022 at 53,438 miles- 10 main dealer services Dpf warning light is on  
Smoking  
Intermittent starting fault

### Tyres



NSF	AUTOGREEN	5.0mm
NSR	GOODYEAR	5.0mm
OSF	AUTOGREEN	5.0mm
OSR	PIRELLI	5.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Cracked  
Over 25mm



3: Wing nsf  
Poor Previous Repair  
Poor Paint



4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Dented  
With Paint Damage



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



8: Wheel nsr  
Scratched  
Up To 50mm



9: Bumper Rear  
Dented  
With Paint Damage



10: Tailgate  
Dented  
With Paint Damage



11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



12: Wheel osr  
Scratched  
Over 50mm



13: Door osr  
Scratched  
Over 25mm Thru Paint



14: Roof  
Scratched  
Over 25mm Thru Paint



15: Door osf  
Dented  
With Paint Damage



16: Door osr  
Scratched  
Over 25mm Thru Paint



17: Wheel osf  
Scratched  
Over 50mm



18: Wing osf  
Chipped  
1 To 5



19: Bumper Front Grill  
Broken  
Replace



20: Fascia Trim  
Damaged  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK