



# VEHICLE INSPECTION REPORT

**YR60CMV**

## Kia Soul 1.6 CRDi 2 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**5**

### Details

Reg. date	10/09/2010	Body Style	Hatchback	Last service miles	69,775
Year	2010	Keys	2	MOT Due	03/01/2027
Mileage	73,781 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	4
Colour	BLUE	Number of stamps	12	Doors	5
VIN	KNAJT813MB7209681	Last service date	08/12/2025		

£100 ADDITIONAL FEE

Last service 08/12/2025 at 69,775 miles- 12 services

### Tyres


NSF	DUNLOP	5.0mm
NSR	INFINITY	5.0mm
OSF	DUNLOP	5.0mm
OSR	INFINITY	5.0mm
Spare		

## Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Poor Previous Repair  
Paint Flake



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Wing nsf  
Poor Previous Repair  
Poor Paint



4: Wheel nsf  
Scratched  
Over 50mm



5: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



6: Door nsf  
Dented  
With Paint Damage



7: Door nsr  
Dented  
With Paint Damage



8: Wheel nsr  
Corroded  
Light



9: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



10: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



11: Bumper Rear  
Poor Previous Repair  
Poor Paint



12: Tailgate  
Dented  
Over 30mm



13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



14: Wheel osr  
Scratched  
Over 50mm



15: Door osr  
Scratched  
Over 25mm Thru Paint



16: Door osr  
Dented  
Between 10mm + 30mm



17: Door osf  
Dented  
Between 10mm + 30mm



18: Door osf  
Chipped  
Edge Chip



19: Wing osf  
Scratched  
Over 25mm Thru Paint



20: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK