



# VEHICLE INSPECTION REPORT

**GU63PKD**

## Toyota Yaris 1.33 VVT-i TR 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**5**

### Details

Reg. date	30/11/2013	Body Style	Hatchback	Last service miles	70,788
Year	2013	Keys	2	MOT Due	01/04/2027
Mileage	89,499 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	9	Doors	5
VIN	VNKKJ3D380A182673	Last service date	13/10/2023		

Last service 13/10/2023 at 70,788 miles- 9 services (3 main dealer) Osr window will not open on driver switches  
 Hail damage  
 Radio faulty

### Tyres


NSF	BUDGET	6.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Park assist camera
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Switches And Controls  
Broken  
Replace



2: Bonnet  
Dented  
Hail - Moderate



3: Bumper Front  
Scratched  
Over 100mm Thru Paint



4: Wing nsf  
Scratched  
Over 25mm Thru Paint




5: Wheel nsf  
Scratched  
Over 50mm



6: Roof  
Dented  
Hail - Severe



7: Door nsf  
Scratched  
Over 25mm Thru Paint



8: Door nsr  
Scratched  
Over 25mm Thru Paint



9: A Post ns  
Dented  
Hail - Moderate



10: B Post ns  
Dented  
Hail - Moderate



11: Tailgate  
Dented  
Hail - Moderate



12: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



13: Door osr  
Scratched  
UpTo 25mm Thru Paint



14: Door osf  
Dented  
Over 30mm



15: Wheel osf  
Scratched  
Over 50mm

16: B Post os  
Dented  
Hail - Moderate

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	Fault
		Steering	OK