



VEHICLE INSPECTION REPORT

FD62JTY

Toyota Avensis 1.8 V-matic TR 5dr M-Drive S

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	10/12/2012	Body Style	Estate	Last service miles	108,541
Year	2012	Keys	3	MOT Due	01/11/2026
Mileage	112,891 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Petrol	Service documents	Service Book	Gears	7
Colour	BLUE	Number of stamps	12		
VIN	SB1EG76L50E085145	Last service date	30/10/2025		

Last service 30/10/2025 at 108,541 miles- 12 main dealer services Small knocking from engine runs fine

Tyres


NSF	NEXEN	5.0mm
NSR	KORMORAN	OK
OSF	NEXEN	5.0mm
OSR	KORMORAN	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Park assist camera
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel osf
Scratched
Over 50mm



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Wing osf
Chipped
1 To 5



6: Door osf
Dented
Over 30mm



7: Door osf
Scratched
UpTo 25mm Thru Paint




8: Door osr
Scratched
Over 25mm Thru Paint



9: Wheel osr
Scratched
Over 50mm



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Tailgate
Scratched
Over 25mm Thru Paint



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Wheel nsr
Scratched
Over 50mm



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Door nsr
Scratched
Over 25mm Thru Paint




16: Door nsf
Scratched
UpTo 25mm Thru Paint



17: Wing nsf
Scratched
Over 25mm Thru Paint



18: Wheel nsf
Scratched
Over 50mm



19: Roof
Dented
Hail - Moderate

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK