



VEHICLE INSPECTION REPORT

RO08DYB

Honda Civic 1.8 i-VTEC Sport 5dr i-SHIFT Auto



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	03/03/2008	Body Style	Hatchback	Last service miles	87,902
Year	2008	Keys	2	MOT Due	27/06/2026
Mileage	90,281 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	7	Doors	5
VIN	SHHFK28407U056761	Last service date	28/06/2025		

Last service 28/06/2025 at 87,902 miles- 7 services
 MOT in 2017 recorded incorrectly on MOT history Driver's window switch for the osr door does not work

Tyres



NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Folding rear seats
- Rear armrest
- Steering wheel reach adjustment
- Curtain airbags
- Alarm
- Trip computer
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Remote central locking
- Radio/CD
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wing osf
Poor Previous Repair
Poor Paint



2: A Post os
Poor Previous Repair
Poor Colour



3: Bonnet
Poor Previous Repair
Poor Paint



4: Wheel Trim nsf
Broken
Replace



5: Bumper Front
Cracked
Over 25mm



6: Wheel nsf
Scratched
Over 50mm



7: Wing nsf
Scratched
Over 25mm Thru Paint



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Poor Previous Repair
Poor Paint



12: Tailgate
Poor Previous Repair
Poor Paint



13: Qtr Panel osr
Poor Previous Repair
Poor Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Poor Previous Repair
Poor Paint



16: B Post os
Poor Previous Repair
Poor Paint



17: Wheel osf
Scratched
Over 50mm



18: Wheel nsr
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	Fault	Radio	OK
		Steering	OK