



VEHICLE INSPECTION REPORT

GX21YPW

Renault Kangoo ML20 44kW 33kWh Business i-Van Auto

| Inspection | | Vehicle | |
|-----------------|----|---------|----------|
| Serious Damage? | No | VAT | Plus VAT |
| | | V5 | Present |



Details

| | | | | | |
|------------|---------------------------|--------------------|--------------|-------------|-----------|
| Reg. date | 21/05/2021 | Service history | Yes | CAP Average | £2,900.00 |
| Year | 2021 | Service documents | Service Book | CAP Below | £2,425.00 |
| Mileage | 34,371 Miles Warranted | Number of stamps | 1 | Gearbox | AUTOMATIC |
| Fuel Type | Electric | Last service date | 29/06/2022 | Gears | 1 |
| Colour | WHITE | Last service miles | 20,200 | Doors | 5 |
| VIN | VF1FW000867090795 | MOT Due | 20/05/2026 | | |
| Body Style | Panel Van | CAP Clean | £3,175.00 | | |

Last Service: 29/06/2022 at 20200 miles. (1 main dealer service) Side door doesn't close properly

Tyres

| | | |
|-------|----------|-------|
| NSF | YOKOHAMA | 2.0mm |
| NSR | MARSHAL | 4.0mm |
| OSF | YOKOHAMA | 3.0mm |
| OSR | BUDGET | 3.0mm |
| Spare | | |

Features


- Bluetooth connection
- Front electric windows
- Rear parking sensor
- Drivers airbag
- Radio/CD
- Central locking
- Air conditioning
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Dented
With Paint Damage




3: Wing nsf
Scratched
Over 25mm Thru Paint




4: Door nsf
Dented
Over 2 UpTo 10mm



5: Door nsr
Dented
2 Or Less UpTo 10mm



6: Door nsf
Scratched
Over 25mm Not Thru Paint




7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm




9: Boot Lid
Chipped
1 To 5



10: Boot Lid
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel osr
Chipped
1 To 5



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Door osf
Dented
With Paint Damage



14: Wing osf
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |