



VEHICLE INSPECTION REPORT

DN17ONV

Ford Focus 1.0 EcoBoost 125 Titanium 5dr

nama
 GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	15/05/2017	Body Style	Hatchback	Last service miles	87,930
Year	2017	Keys	2	MOT Due	13/10/2026
Mileage	90,442 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	7	Doors	5
VIN	WF05XXGCC5HM79325	Last service date	11/06/2025		

Last service 11/06/2025 at 87,930 miles- 7 services (6 main dealer) Bumper bonnet and wings out of line, EML on, catalyst system efficiency below threshold

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm



Spare

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Switches And Controls
Broken
Replace



2: Roof Lining
Scuffed
Over 25mm



3: Bumper Front
Poor Previous Repair
Poor Paint




4: Bonnet
Poor Previous Repair
Poor Paint



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Dented
Between 10mm + 30mm




9: Door nsr
Chipped
Edge Chip



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Tailgate
Poor Previous Repair
Poor Paint



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Dented
2 Or Less Up To 10mm



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osr
Dented
Between 10mm + 30mm



18: Door osf
Chipped
Edge Chip



19: Door osf
Dented
Over 30mm



20: Wheel osf
Scratched
Over 50mm



21: Wing osf
 Scratched
 Over 25mm Thru Paint



22: Roof
 Scratched
 Over 25mm Thru Paint



23: B Post os
 Scratched
 Over 25mm Thru Paint



24: Wing osf
 Dented
 Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK