



VEHICLE INSPECTION REPORT

AJ72KXS

Volkswagen Polo 1.0 TSI Style 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/12/2022	Body Style	Hatchback	Last service miles	2
Year	2022	Keys	2	MOT Due	12/10/2026
Mileage	12,040 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	BLACK	Number of stamps	2	Doors	5
VIN	WVVZZZAWZPU005721	Last service date	06/12/2024		

LAST SERVICE 06/12/2024 @ 4,812 MILES (2 SERVICES, BOTH MAIN DEALER)

Tyres

NSF	FALKEN	6.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Door nsf
Chipped
1 To 5



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Door nsr
Poor Previous Repair
Poor Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Wheel osr
Scratched
Over 50mm




11: Door osr
Poor Previous Repair
Poor Paint



12: Door osf
Scratched
Over 25mm Thru Paint



13: Screen Front
Chipped
Over 10mm



14: Roof
Chipped
1 To 5



15: Wing osf
Chipped
1 To 5



16: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK