

VEHICLE INSPECTION REPORT

HV03NTY

Volkswagen Golf Mk4 MATCH

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	30/04/2003	Body Style	Hatchback	Last service miles	110,873
Year	2003	Keys	1	MOT Due	30/04/2027
Mileage	121,342 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREEN	Number of stamps	20	Doors	5
VIN	WVWZZZ1JZ3P395712	Last service date	28/01/2025		

Last service 28/01/2025 at 110,873 miles- 20 services (10 main dealer) Book and print

Tyres

NSF	LAUFENN	5.0mm
NSR	YOKOHAMA	5.0mm
OSF	LAUFENN	5.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Remote central locking
- Radio/Cassette
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Cloth seat trim
- Radio/CD
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Corroded
Light



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Dented
Over 30mm



6: A Post ns
Scratched
Over 25mm Thru Paint



7: Roof
Poor Previous Repair
Paint Flake



8: Door nsr
Dented
Between 10mm + 30mm



9: Door nsr
Chipped
Multiple Chips



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Lamp nsr
Broken
Replace



14: Qtr Panel osr
Dented
With Paint Damage



15: Wheel osr
Corroded
Light



16: Door osr
Dented
Over 30mm



17: Sill os
Scratched
Over 25mm Thru Paint



18: Door osf
Chipped
Edge Chip



19: Wing osf
Dented
Between 10mm + 30mm



20: Wing osf
Scratched
Over 25mm Thru Paint



21: Wheel osf
Corroded
Light



22: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK