



VEHICLE INSPECTION REPORT

DP67GFJ

Nissan Qashqai 1.2 DiG-T N-Connecta 5dr

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/01/2018	Body Style	Hatchback	Last service miles	46,595
Year	2018	Keys	1	Gearbox	MANUAL
Mileage	50,514 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	Petrol	Service documents	Service Book	Doors	5
Colour	RED	Number of stamps	6		
VIN	SJNFEAJ11U2224022	Last service date	23/04/2025		

Last service 23/04/2025 at 46,595 miles- 6 services (5 main dealer)
 MOT FAILURE Collision warning system faulty
 Abs and traction control warning lights are on
 Stop start system faulty

Tyres



NSF	NEXEN	6.0mm
NSR	CONTINENTAL	5.0mm
OSF	NEXEN	6.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Door nsf
Dented
Over 30mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Dented
With Paint Damage



13: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



14: Door osf
Scratched
Over 25mm Thru Paint



15: Wing of
Poor Previous Repair
Poor Paint



16: Wheel of
Scratched
Over 50mm



17: A Post of
Poor Previous Repair
Poor Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK