



VEHICLE INSPECTION REPORT

RJ62YVD

Volkswagen Golf 1.4 TSI SE 5dr DSG

nama
 GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	11/02/2013	Body Style	Hatchback	MOT Due	26/01/2027
Year	2013	Keys	2	Gearbox	SEMI AUTO
Mileage	67,474 Miles Warranted	Service history	Yes	Gears	7
Fuel Type	Petrol	Service documents	Printout	Doors	5
Colour	BLACK	Number of stamps	8		
VIN	WVWZZZAUZDW060676	Last service date	27/01/2026		

£90 ADDITIONAL FEE

Last service 27/01/2026 mileage recorded incorrectly - 8 main dealer services

Last MOT and service on 26/01/2027 recorded incorrectly at 103,024 miles Bonnet and osf wing out of line

Error stop start system message displayed

Tyres


NSF	AVON	6.0mm
NSR	HANKOOK	6.0mm
OSF	AVON	6.0mm
OSR	NEXEN	6.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Up To 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsr
Scratched
Up To 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: B Post ns
Dented
Between 10mm + 30mm



10: A Post ns
Dented
Between 10mm + 30mm



11: Roof
Dented
Over 30mm



12: Wheel nsr
Scratched
Over 50mm



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Bumper Rear
Scratched
Over 100mm Thru Paint




15: Qtr Panel nsr
Dented
With Paint Damage



16: Wheel osr
Scratched
Up To 50mm



17: Door osr
Dented
Between 10mm + 30mm



18: Door osf
Scratched
Over 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm



20: Wing osf
Chipped
1 To 5



21: Roof Lining
Torn
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK