



VEHICLE INSPECTION REPORT

GY20HSA

Volkswagen Polo 1.0 TSI 95 Match 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	16/06/2020	Body Style	Hatchback	Last service miles	42,520
Year	2020	Keys	2	MOT Due	26/03/2027
Mileage	43,666 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	GREY	Number of stamps	6	Doors	5
VIN	WVVZZZAWZLU079267	Last service date	27/03/2026		

£90 ADDITIONAL FEE

Last service 27/03/2026 at 42,520 miles- 6 services

Tyres

NSF	RAPID	5.0mm
NSR	GOODYEAR	3.0mm
OSF	RAPID	5.0mm
OSR	GOODYEAR	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Trip computer
- Front fog lights
- Folding rear seats
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Alarm
- Cruise control
- Rear parking sensor
- Radio/CD
- Heated door mirrors
- Front electric windows
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm




2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Dented
Between 10mm + 30mm



7: Door nsr
Scratched
UpTo 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Dented
Between 10mm + 30mm



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
Chipped
Edge Chip



16: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



17: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK