



VEHICLE INSPECTION REPORT

WJ70EHD

Seat Leon 1.5 TSI EVO FR 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	03/02/2021	Body Style	Hatchback	Last service miles	71,270
Year	2021	Keys	1	MOT Due	02/02/2027
Mileage	80,877 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	6	Doors	5
VIN	VSSZZZKLZMR048900	Last service date	14/01/2026		

£90 ADDITIONAL FEE
 LAST SERVICE 14/01/2026 @ 71,270 MILES (6 SERVICES, 2 MAIN DEALER)

Tyres


NSF	BUDGET	2.0mm
NSR	MICHELIN	4.0mm
OSF	BUDGET	2.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Trip computer
- Heated door mirrors
- Front armrest
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Alarm
- Cruise control
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Climate control
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Dented
Over 30mm



5: Door nsr
Dented
Between 10mm + 30mm



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Qtr Panel osr
Dented
Between 10mm + 30mm



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Door osf
Dented
Between 10mm + 30mm



10: Screen Front
Chipped
UpTo 10mm



11: Roof
Chipped
1 To 5



12: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK