



VEHICLE INSPECTION REPORT

MJ69FJZ

Peugeot 2008 1.2 PureTech 130 GT Line 5dr EAT6

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/09/2019	Body Style	Hatchback	Last service miles	18,742
Year	2019	Keys	2	MOT Due	29/09/2026
Mileage	19,727 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	6	Doors	5
VIN	VF3CUHNS4KY189111	Last service date	02/01/2026		

LAST SERVICE 02/01/2026 @ 18,742 MILES (6 SERVICES, ALL MAIN DEALER)

Tyres

NSF	TRIANGLE	6.0mm
NSR	TRIANGLE	6.0mm
OSF	TRIANGLE	6.0mm
OSR	TRIANGLE	6.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos






Condition Check




Damage Photos



1: Bumper Front
Poor Previous Repair
Poor Paint



2: Other
N/A
N/A



3: Bonnet
Chipped
1 To 5



4: Wing nsf
Poor Previous Repair
Poor Paint



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Poor Previous Repair
Poor Paint



7: Sill Panel Trim ns
Scuffed (Unpainted)
Over 100mm



8: Wheel nsr
Scratched
Over 50mm



9: Door nsr
Poor Previous Repair
Poor Paint



10: Door osr
Dented
Over 30mm




11: Door osf
Chipped
Edge Chip



12: Wing osf
Chipped
1 To 5



13: Wheel osf
Scratched
Over 50mm



14: Screen Front
Chipped
UpTo 10mm



15: Qtr Panel nsr
 Poor Previous Repair
 Poor Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK