



# VEHICLE INSPECTION REPORT

**GJ60VWF**

## Renault Grand Scenic 1.5 dCi 110 Privilege TomTom 5dr

nama  
 GRADE  
**5**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	24/12/2010	VIN	VF1JZ1GB644393188	Number of stamps	9
Year	2010	Body Style	MPV	Last service date	28/07/2025
Mileage	122,762 Miles Warranted	Keys	2	MOT Due	02/01/2027
Fuel Type	Diesel	Service history	Yes	Gearbox	MANUAL
Colour	BEIGE	Service documents	Printout	Gears	6

### £100 ADDITIONAL FEE

last service 28/7/25 mileage not recorded (9 services 5 main dealer) Service light display  
 Exhaust blowing

### Tyres

NSF	MATADOR	6.0mm
NSR	MATADOR	6.0mm
OSF	MATADOR	6.0mm
OSR	ROVELO	6.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Rear wiper
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Service indicator
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Scuffed  
Over 25mm



2: Bonnet  
Chipped  
1 To 5



3: Bumper Front  
Scratched  
Over 100mm Thru Paint



4: Fog Lamp Surround ns  
Scratched (Painted)  
Over 25mm Thru Paint



5: Wing nsf  
Scratched  
Over 25mm Thru Paint



6: Wheel nsf  
Scratched  
Over 50mm



7: Door nsf  
Dented  
Over 30mm



8: Flasher Side Repeater ns  
Broken  
Replace



9: Door nsr  
Chipped  
Multiple Chips



10: Door nsr  
Dented  
Between 10mm + 30mm



11: Wheel nsr  
Scratched  
Over 50mm



12: Qtr Panel nsr  
Dented  
With Paint Damage



13: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



14: Tailgate  
Scratched  
UpTo 25mm Thru Paint



15: Roof  
Dented  
Over 30mm



16: Wheel osr  
Scratched  
Over 50mm



17: Qtr Panel osr  
Dented  
With Paint Damage



18: Door osr  
Chipped  
1 To 5



19: Door osr  
Dented  
Between 10mm + 30mm



20: Door osf  
Chipped  
Edge Chip




21: Door osf  
Dented  
2 Or Less UpTo 10mm



22: Wheel osf  
Scratched  
Over 50mm



23: Wing osf  
Scratched  
Over 25mm Thru Paint



24: Screen Front  
Cracked  
Replace



25: Roof Lining  
Scuffed  
Over 25mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK