



VEHICLE INSPECTION REPORT

OE61BDZ

Ford C-Max 1.6 TDCi Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/12/2011	Body Style	MPV	Last service miles	89,090
Year	2011	Keys	2	MOT Due	18/08/2026
Mileage	100,307 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	9		
VIN	WFOJXXWPBJBM86686	Last service date	08/08/2024		

£100 ADDITIONAL FEE
 LAST SERVICE 08/08/2024 @ 89,090 MILES (9 SERVICES, 3 MAIN DEALER)

Tyres

NSF	AVON	6.0mm
NSR	AVON	6.0mm
OSF	AVON	6.0mm
OSR	AVON	6.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Space saver spare wheel
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: A Post ns
Chipped
1 To 5



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Chipped
1 To 5



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Bumper Rear
Insecure
Action Required



11: Wheel osr
Scratched
Over 50mm



12: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



13: Door osr
Scratched
UpTo 25mm Thru Paint



14: Door osr
Dented
2 Or Less UpTo 10mm



15: Door osf
Dented
Between 10mm + 30mm



16: Wing osf
Chipped
1 To 5



17: Wheel osf
Scratched
Up To 50mm



18: Roof
Scratched
Over 25mm Thru Paint



19: Bumper Reflector osr
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK