

VEHICLE INSPECTION REPORT

EJ60OLE

Hyundai I10 1.2 Comfort 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
 GRADE
4

Details

Reg. date	26/11/2010	Body Style	Hatchback	Last service miles	46,632
Year	2010	Keys	2	MOT Due	05/12/2026
Mileage	58,500 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	4	Doors	5
VIN	MALAN51CLAM734152	Last service date	07/06/2021		

£100 ADDITIONAL FEE

Last service 07/06/2021 at 46,632 miles- 4 services . Book and print High biting point on clutch

Tyres


NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- Drivers airbag
- Remote central locking
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Side airbags
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Dented
2 Or Less UpTo 10mm



7: Door nsr
Chipped
1 To 5



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Poor Previous Repair
Poor Paint



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Wheel nsr
Scratched
Up To 50mm



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Scratched
Over 25mm Thru Paint



15: Wing of
Chipped
1 To 5



16: Wheel of
Scratched
Over 50mm



17: Aerial
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK