



VEHICLE INSPECTION REPORT

YP08UDV

Ford Mondeo 2.3 Zetec 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	30/05/2008	Body Style	Hatchback	MOT Due	03/06/2027
Year	2008	Service history	Yes	Gearbox	AUTOMATIC
Mileage	60,142 Miles Warranted	Service documents	Service Book	Gears	6
Fuel Type	Petrol	Number of stamps	5	Doors	5
Colour	BLACK	Last service date	05/09/2024		
VIN	WF0EXXGBBE8G13586	Last service miles	56,170		

£90 ADDITIONAL FEE
 LAST SERVICE 05/09/2024 @ 56,170 MILES (5 SERVICES)

Tyres


NSF	BUDGET	2.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	2.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Alarm
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Trip computer
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Up To 50mm



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Poor Previous Repair
Poor Paint




8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Tailgate
Dented
Over 30mm



10: Qtr Panel osr
Poor Previous Repair
Poor Paint



11: Door osr
Scratched
Over 25mm Thru Paint



12: Door osr
Dented
Over 30mm



13: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK