

# VEHICLE INSPECTION REPORT

**NU08KBJ**

## Nissan Micra 1.2 Acenta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	27/03/2008	Body Style	Hatchback	Last service miles	21,631
Year	2008	Keys	2	MOT Due	23/04/2027
Mileage	52,707 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	1	Doors	5
VIN	SJNFBAK12U3043186	Last service date	22/11/2011		

Last service 22/11/2011 at 21,631 miles- 1 main dealer service

### Tyres



NSF	BUDGET	5.0mm
NSR	SUNNY	5.0mm
OSF	BUDGET	5.0mm
OSR	SUNNY	5.0mm
Spare		

### Features


- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Steel wheels

### Photos





## Condition Check



## Damage Photos



1: Other  
N/A  
N/A



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



5: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



6: Door nsf  
Dented  
With Paint Damage



7: Door nsr  
Dented  
With Paint Damage




8: Qtr Panel nsr  
Dented  
With Paint Damage




9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Qtr Panel osr  
Dented  
Over 30mm



11: Door osr  
Dented  
Between 10mm + 30mm




12: Door osf  
Dented  
Over 30mm



13: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



14: Wing osf  
Scratched  
Over 25mm Thru Paint



15: Screen Front  
Scratched  
Over 30mm



16: Roof  
Chipped  
Multiple Chips



17: Wiper Rear  
Broken  
Replace



18: Switches And Controls  
Broken  
Replace

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK