

**LH09AUC**

# VEHICLE INSPECTION REPORT

## Nissan Note 1.6 Tekna 5dr Auto

nama  
 GRADE  
**5**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	23/06/2009	VIN	SJNFCAE11U2015065	Last service date	30/05/2025
Year	2009	Body Style	MPV	Last service miles	132,403
Mileage	146,787 Miles Warranted	Service history	Yes	MOT Due	23/06/2026
Fuel Type	Petrol	Service documents	Service Book	Gearbox	AUTOMATIC
Colour	SILVER	Number of stamps	14	Gears	4

Last Service - 30.05.2025 at 132403 miles (14 main dealer services)


### Tyres


NSF	AVON	6.0mm
NSR	AUTOGREEN	5.0mm
OSF	AVON	6.0mm
OSR	AUTOGREEN	4.0mm
Spare		

### Features


- Cruise control
- Trip computer
- Front fog lights
- Front electric windows
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Rear wiper
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Alarm

### Photos





## Condition Check



## Damage Photos



1: Wing of  
Scratched  
Over 25mm Thru Paint



2: Wheel of  
Scratched  
Over 50mm



3: Bumper Front  
Scratched  
Over 100mm Thru Paint



4: Bonnet  
Chipped  
Multiple Chips



5: Wheel nsf  
Scratched  
Over 50mm



6: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



7: Roof  
Scratched  
Over 25mm Thru Paint



8: Door nsf  
Scratched  
Over 25mm Thru Paint



9: Door nsr  
Dented  
2 Or Less UpTo 10mm



10: Door nsr  
Scratched  
Over 25mm Thru Paint



11: Bumper Rear  
Dented  
With Paint Damage



12: Wheel osr  
Scratched  
Over 50mm



13: Qtr Panel osr  
Poor Previous Repair  
Rippled UpTo 30%



14: Door osr  
Dented  
Over 30mm



15: Door osr  
 Scratched  
 Over 25mm Thru Paint

16: Door osf  
 Dented  
 Between 10mm + 30mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK