



VEHICLE INSPECTION REPORT

NU16DYX

Nissan Qashqai 1.6 dCi Tekna 5dr Xtronic

Non Runner Inspection

Serious Damage?	No	Vehicle VAT	Margin
		V5	Present



Details

Reg. date	22/04/2016	Body Style	Hatchback	Last service miles	142,152
Year	2016	Keys	2	MOT Due	21/04/2027
Mileage	142,914 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Diesel	Service documents	Service Book	Gears	1
Colour	RED	Number of stamps	10	Doors	5
VIN	SJNFDAJ11U1643182	Last service date	16/04/2026		

NON RUNNER

Last service 16/04/2026 at 142,152 miles- 10 services (9 main dealer) Eml light is on
 Gearbox faulty
 Car in limp mode

Tyres

NSF	BRIDGESTONE	4.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	4.0mm
OSR	BRIDGESTONE	5.0mm

Spare

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Door osr
Dented
Between 10mm + 30mm



12: Door osf
Chipped
Multiple Chips



13: Door osf
Dented
Between 10mm + 30mm



14: Door osf
Chipped
Multiple Chips



15: Wing of
Chipped
Multiple Chips

16: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK