



# VEHICLE INSPECTION REPORT

**BW68NKF**

## MG Mg 3 EXCITE VTI-TECH

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	02/01/2019	Body Style	Hatchback	Last service miles	24,568
Year	2019	Keys	2	MOT Due	17/03/2027
Mileage	55,425 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLUE	Number of stamps	3	Doors	5
VIN	SDPZ1BBDAJS150948	Last service date	15/03/2023		

£90 ADDITIONAL FEE

LAST SERVICE 15/03/2023 @ 24,568 MILES (3 SERVICES, ALL MAIN DEALER) Eml light is on  
Car been plugged in and detected  
Ambient air temperature sensor circuit low input

### Tyres

NSF	NEXEN	5.0mm
NSR	MAXXIS	Damaged
OSF	NEXEN	6.0mm
OSR	SUNNY	5.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Cloth seat trim
- PAS
- Digital radio
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Tyre nsr  
Damaged  
Replace



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Scratched  
Over 100mm Thru Paint



4: Bumper Front Moulding  
Broken  
Replace



5: Bumper Front Grill  
Missing  
Replace



6: Wheel nsf  
Scratched  
Over 50mm



7: Wing nsf  
Chipped  
1 To 5



8: Door nsf  
Chipped  
1 To 5



9: Door nsf  
Chipped  
Edge Chip



10: Door nsr  
Scratched  
Over 25mm Thru Paint



11: Wheel nsr  
Scratched  
Over 50mm



12: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



13: Other  
N/A  
N/A



14: Tailgate  
Scratched  
Over 25mm Thru Paint



15: Bumper Rear  
Chipped  
1 To 5



16: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



17: Wheel osr  
Scratched  
Over 50mm



18: Door osr  
Dented  
With Paint Damage



19: Door osf  
Chipped  
1 To 5



20: Door osf  
Chipped  
Edge Chip



21: Wing of  
Dented  
With Paint Damage



22: Wheel of  
Scratched  
Over 50mm



23: Roof  
Rusted  
Over 5mm

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK