

VEHICLE INSPECTION REPORT

FL63LLM

Vauxhall Meriva 1.4T 16V Exclusiv 5dr Auto

nama
 GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	11/10/2013	Colour	BROWN	Service history	None
Year	2013	VIN	W0LSD9EM9E4015415	MOT Due	24/02/2027
Mileage	53,086 Miles Warranted	Body Style	MPV	Gearbox	AUTOMATIC
Fuel Type	Petrol	Keys	1	Gears	6

£90 ADDITIONAL FEE
 No service history Oil light is on


Tyres

NSF	BUDGET	5.0mm
NSR	TOYO	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Cruise control
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Service indicator
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Steel wheels
- Rear parking sensor
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Air Vents osf
Damaged
Replace



2: Other
N/A
N/A



3: Bonnet
Chipped
1 To 5



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Dented
Between 10mm + 30mm



8: Door osf
Chipped
1 To 5



9: Qtr Panel nsr
Dented
Over 30mm



10: Door nsr
Dented
With Paint Damage



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Parking Sensor Rear
Missing
Replace



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
Scratched
UpTo 25mm Thru Paint



16: Wing nsf
Scratched
Over 25mm Thru Paint



17: Roof
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK