



VEHICLE INSPECTION REPORT

GU10UPH

Ford Fiesta 1.4 Zetec 5dr

nama
 GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	05/03/2010	Body Style	Hatchback	Last service miles	49,363
Year	2010	Keys	2	MOT Due	11/03/2027
Mileage	106,449 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	BLUE	Number of stamps	2	Doors	5
VIN	WF0JXXWPJJAL72414	Last service date	09/02/2017		

£90 ADDITIONAL FEE

Last service 09/02/2017 at 49,363 miles- 2 services

Tyres

NSF	DOUBLESTAR	5.0mm
NSR	GT RADIAL	6.0mm
OSF	DOUBLESTAR	5.0mm
OSR	ROADSTONE	5.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Fogdriving Lamp nsf
Broken
Replace



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Dented
Between 10mm + 30mm



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



10: Bumper Rear
Cracked
Over 25mm



11: Reflector nsr
Broken
Replace



12: Tailgate
Dented
Over 30mm



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Wheel nsr
Scratched
Over 50mm



15: Door osr
Dented
Between 10mm + 30mm



16: Door osr
Chipped
1 To 5



17: Door osf
Scratched
Over 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm



19: Wing osf
Chipped
1 To 5



20: Other
N/A
N/A



21: B Post os
 Scratched
 Rusted



22: Roof
 Scratched
 Over 25mm Thru Paint



23: Rear TowEye Cvr
 Missing
 Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK