



VEHICLE INSPECTION REPORT

BX63EZM

Ford Focus 1.0 EcoBoost Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	13/09/2013	Body Style	Hatchback	Last service miles	73,550
Year	2013	Keys	2	MOT Due	10/10/2026
Mileage	85,209 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	6	Doors	5
VIN	WF0KXXGCBKDA32065	Last service date	12/10/2023		

£100 ADDITIONAL FEE

LAST SERVICE 12/10/2023 @ 73,550 MILES (6 SERVICES, 5 MAIN DEALER) Poor brakes

Roof is faded

Tyres

NSF	SUNNY	3.0mm
NSR	BUDGET	4.0mm
OSF	SUNNY	3.0mm
OSR	LAUFENN	4.0mm

Spare

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wing ofsf
Chipped
1 To 5



2: Wheel ofsf
Scratched
Over 50mm



3: Wing osf
Scratched
UpTo 25mm Thru Paint



4: Door osf
Chipped
1 To 5



5: Door osr
Scratched
UpTo 25mm Thru Paint



6: Door osr
Chipped
1 To 5



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Wheel osr
Scratched
Up To 50mm



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Door nsr
Dented
With Paint Damage



13: Door nsf
Scratched
Over 25mm Thru Paint



14: Wing nsf
Dented
With Paint Damage



15: Wheel nsf
Scratched
Over 50mm



16: Bumper Front
Poor Previous Repair
Poor Paint



17: Bonnet
Scratched
Over 25mm Thru Paint



18: Screen Front
Chipped
UpTo 10mm



19: Door osr
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK