



# VEHICLE INSPECTION REPORT

**VN64XMP**

## Nissan Pulsar 1.5 dCi N-Tec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	31/10/2014	Body Style	Hatchback	Last service miles	155,759
Year	2014	Keys	2	MOT Due	11/03/2027
Mileage	160,778 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	10	Doors	5
VIN	VSKDAAC13U0008637	Last service date	19/11/2025		

£100 ADDITIONAL FEE

LAST SERVICE 19/11/2025 @ 155,759 MILES (10 SERVICES, 5 MAIN DEALER - BOOK & PRINT) Engine misfires

### Tyres


NSF	SUNNY	5.0mm
NSR	LAUFENN	5.0mm
OSF	SUNNY	5.0mm
OSR	LAUFENN	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Dented  
With Paint Damage



3: Wing nsf  
Chipped  
1 To 5



4: Wheel nsf  
Scratched  
Over 50mm




5: Door nsf  
Chipped  
1 To 5



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



10: Tailgate  
Dented  
With Paint Damage



11: Wheel osr  
Scratched  
Over 50mm



12: Door osr  
Dented  
With Paint Damage



13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



14: Door osf  
Dented  
Over 30mm



15: Wheel of  
Scratched  
Over 50mm

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK