



VEHICLE INSPECTION REPORT

RJ16GZV

Renault Kadjar 1.5 dCi Dynamique S Nav 5dr

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	04/06/2016	Body Style	Hatchback	Last service miles	61,512
Year	2016	Keys	2	MOT Due	11/07/2026
Mileage	95,697 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	4	Doors	5
VIN	VF1RFE00855198533	Last service date	15/12/2022		

Last service 15/12/2022 at 61,512 miles- 4 services (3 main dealer) Parking brake faulty
 Service spanner displayed

Tyres

NSF	KUMHO	3.0mm
NSR	PIRELLI	4.0mm
OSF	KUMHO	3.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Service indicator
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Chipped
1 To 5



10: Bumper Rear
Scratched
Over 100mm Thru Paint




11: Tailgate
Dented
With Paint Damage



12: Qtr Panel osr
Scratched
Up To 25mm Thru Paint



13: Door osr
Chipped
1 To 5



14: Door osf
Dented
Between 10mm + 30mm



15: Wing of
Scratched
Up To 25mm Thru Paint



16: Wheel of
Scratched
Over 50mm



17: Roof
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	Fault	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK