



VEHICLE INSPECTION REPORT

LJ11AWP

Nissan Qashqai 1.6 [117] Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	11/03/2011	Body Style	Hatchback	Last service miles	26,290
Year	2011	Keys	2	MOT Due	Expired
Mileage	132,591 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	3	Doors	5
VIN	SJNFAAJ10U2240897	Last service date	21/01/2015		

Last service 21/01/2015 at 26,290 miles- 3 services (2 main dealer)

MOT EXPIRED

Tyres


NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Radio/CD
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door nsr
Dented
With Paint Damage



10: Wheel nsr
Corroded
Light



11: Bumper Rear
Poor Previous Repair
Paint Flake



12: Tailgate
Dented
Over 30mm



13: Tailgate Trim Panel
Broken
Replace



14: C Post os
Dented
Between 10mm + 30mm



15: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



16: Qtr Panel osr
Dented
Between 10mm + 30mm



17: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Door osr
Dented
Between 10mm + 30mm



20: Door osr
Scratched
Over 25mm Thru Paint



21: Door osf
 Scratched
 Over 25mm Thru Paint



22: Wheel osf
 Scratched
 Up To 50mm



23: Door Mirror Assy osf
 Scratched (Painted)
 UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK