



# VEHICLE INSPECTION REPORT

**WD66XEP**

## Renault Captur 1.5 dCi 90 Dynamique Nav 5dr

nama  
GRADE  
**4**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	23/02/2017	Body Style	Hatchback	Last service miles	103,665
Year	2017	Keys	2	MOT Due	22/02/2027
Mileage	115,982 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	5
Colour	BLUE	Number of stamps	6	Doors	5
VIN	VF12RAJ1A56962277	Last service date	03/10/2025		

£90 ADDITIONAL FEE

Last service 03/10/2025 at 03/10/2025 at 103,665 miles- 6 services Front suspension knocking

### Tyres

NSF	RAPID	Damaged
NSR	RAPID	5.0mm
OSF	RAPID	3.0mm
OSR	RAPID	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Bumper Front  
Insecure  
Action Required



4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Scratched  
Over 25mm Thru Paint



6: Wing Front Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



7: Flasher Side Repeater ns  
Broken  
Replace



8: Door nsf  
Dented  
Between 10mm + 30mm



9: Door nsf  
Chipped  
Multiple Chips



10: Door nsr  
Dented  
With Paint Damage



11: Door Moulding nsr  
Scuffed (Unpainted)  
Over 100mm



12: Qtr Panel Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



13: Wheel nsr  
Scratched  
Over 50mm



14: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint



15: Tailgate  
Dented  
Between 10mm + 30mm




16: Qtr Panel osr  
Dented  
Between 10mm + 30mm



17: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



18: Door osr  
Scratched  
Over 25mm Thru Paint



19: Door osf  
Scratched  
Over 25mm Thru Paint



20: Door Mirror Assy osf  
Scratched (Painted)  
UpTo 25mm Thru Paint



21: Wheel osf  
Scratched  
Over 50mm



22: A Post os  
Chipped  
1 To 5



23: Tyre nsf  
Damaged  
Replace

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK