



VEHICLE INSPECTION REPORT

GM65NMZ

Dacia Sandero 0.9 TCe Laureate Prime 5dr [Start Stop]

nama
 GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	29/01/2016	Body Style	Hatchback	Last service miles	38,824
Year	2016	Keys	2	MOT Due	12/02/2027
Mileage	61,048 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	BLUE	Number of stamps	5	Doors	5
VIN	UU15SDA1553751714	Last service date	13/01/2023		

Last service 13/01/2023 at 38,824 miles- 5 services Zigzag warning light displayed

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm


Spare

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Poor Previous Repair
Paint Flake



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Dented
With Paint Damage



8: Door nsr
Dented
Between 10mm + 30mm



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Dented
With Paint Damage



11: Tailgate
Poor Previous Repair
Rippled UpTo 30%



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Door osr
Scratched
Over 25mm Thru Paint




14: Door nsf
Dented
With Paint Damage



15: Wing of
Chipped
1 To 5



16: Wheel of
Scratched
Up To 50mm



17: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK