



VEHICLE INSPECTION REPORT

GU66DHF

Fiat 500x 1.4 Multiair Cross 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/09/2016	Body Style	Hatchback	MOT Due	28/09/2026
Year	2016	Keys	1	Gearbox	MANUAL
Mileage	103,977 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	Petrol	Service documents	Service Book	Doors	5
Colour	BLUE	Number of stamps	11		
VIN	ZFA3340000P502650	Last service miles	98,744		

£90 ADDITIONAL FEE.

Last Service - unknown at 98744 miles (11 services)

Tyres

NSF	HANKOOK	4.0mm
NSR	HANKOOK	4.0mm
OSF	HANKOOK	3.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos




1: Wheel osf
Corroded
Light



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Door osf
 Scratched
 Over 25mm Thru Paint



4: Door osr
 Chipped
 1 To 5



5: Wheel osr
 Corroded
 Light



6: Qtr Panel osr
 Dented
 2 Or Less UpTo 10mm




7: Bumper Rear
 Scratched
 25 to 100mm Thru Paint



8: Bumper Rear
 Chipped
 Multiple Chips



9: Tailgate
Chipped
1 To 5



10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Wheel nsr
Corroded
Light



12: Door nsr
Dented
With Paint Damage



13: Door nsf
Chipped
Multiple Chips



14: Wing nsf
Chipped
1 To 5



15: Wing nsf
Scratched
Over 25mm Not Thru Paint



16: Wheel nsf
Corroded
Light



17: Bonnet
Chipped
Multiple Chips



18: Bumper Front
Poor Previous Repair
Poor Paint



19: Roof
Poor Previous Repair
Paint Flake

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK