



VEHICLE INSPECTION REPORT

CN13VZY

Ford Focus 1.6 125 Zetec 5dr Powershift

nama
 GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	02/03/2013	VIN	WF0KXXGCBKDJ56503	MOT Due	30/07/2026
Year	2013	Body Style	Hatchback	Gearbox	AUTOMATIC
Mileage	107,397 Miles Warranted	Keys	2	Gears	6
Fuel Type	Petrol	Service history	Yes	Doors	5
Colour	BLUE	Service documents	Service Book		

Last service 26/03/2025 at 97,978 miles- 11 services (7 main dealer) Exhaust blowing
 Parking sensors faulty

Tyres


NSF	LAUFENN	Damaged
NSR	BARUM	5.0mm
OSF	BARUM	5.0mm
OSR	BARUM	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Space saver spare wheel
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Dented
With Paint Damage



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm




4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint




6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
Between 10mm + 30mm



8: Door Mirror Assy nsf
Scratched (Painted)
Up To 25mm Thru Paint



9: A Post ns
Scratched
UpTo 25mm Thru Paint



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Rusted



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Rear TowEye Cvr
Missing
Replace



14: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



15: Tailgate
Scratched
Over 25mm Thru Paint



16: Qtr Panel osr
Dented
With Paint Damage




17: Wheel osr
Scratched
Up To 50mm



18: Door osr
Scratched
Over 25mm Thru Paint



19: Door osr
Dented
Over 30mm



20: Door osf
Scratched
Over 25mm Thru Paint



21: Wing osf
Dented
With Paint Damage



22: Wheel osf
Scratched
Over 50mm



23: Flasher Side Repeater os
Broken
Replace



24: Screen Front
Chipped
UpTo 10mm



25: Tyre nsf
Damaged
Replace



26: Sill Panel Trim os
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK