



VEHICLE INSPECTION REPORT

GX67XWT

Nissan Juke 1.2 DiG-T Tekna Pulse 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	01/09/2017	Body Style	Hatchback	Last service miles	48,482
Year	2017	Keys	2	MOT Due	31/08/2026
Mileage	62,176 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	6	Doors	5
VIN	SJNFEAF15U7327450	Last service date	14/04/2025		

£90 ADDITIONAL FEE

Last service 14/04/2025 at 48,482 miles- 6 services (5 main dealer) Book and print

Tyres


NSF	BRIDGESTONE	Damaged
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	2.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Navigation system
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Chipped
1 To 5



5: A Post ns
Scratched
UpTo 25mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Door nsf
Dented
Between 10mm + 30mm



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Door nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Chipped
1 To 5



13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Wheel osf
Scratched
Over 50mm



16: Door osf
Chipped
1 To 5



17: Door osf
Chipped
Edge Chip



18: Door osf
Dented
Between 10mm + 30mm



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm



21: Tyre nsf
 Damaged
 Replace

Interior

Carpet Condition
Seat Condition

Average
 Average

Upholstery Condition
Odour

Average
 No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK