



VEHICLE INSPECTION REPORT

LN67DZC

Nissan X-Trail 1.6 dCi N-Vision 5dr 4WD [7 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/09/2017	Keys	2	CAP Clean	£5,150.00
Year	2017	Service history	Yes	CAP Average	£4,525.00
Mileage	116,953 Miles Warranted	Service documents	Printout	CAP Below	£3,875.00
Fuel Type	Diesel	Number of stamps	9	Gearbox	MANUAL
Colour	BLUE	Last service date	08/10/2024	Gears	6
VIN	JN1JCNT32U0015925	Last service miles	106,460		
Body Style	Estate	MOT Due	14/02/2026		

£65 ADDITIONAL FEE TIMING COVER REPLACED 13/05/2024 @ 95954 MILES Last service 08/10/2024 @ 106460 miles (9 SERVICES 2 MAIN DEALER) Noisy engine

Tyres


NSF	HANKOOK	3.0mm
NSR	GOODYEAR	2.0mm
OSF	HANKOOK	3.0mm
OSR	GOODYEAR	3.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- PAS
- Telephone
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Trip computer
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Rear wiper
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Up To 50mm



4: Wing nsf
Chipped
1 To 5




5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Poor Previous Repair
Paint Flake



7: Door nsr
Chipped
1 To 5



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Up To 50mm




10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Dented
With Paint Damage



12: Boot Lid
Scratched
UpTo 25mm Thru Paint



13: Boot Lid
Scratched
Over 25mm Not Thru Paint



14: Wheel osr
Scratched
Up To 50mm

No Image



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

16: Door osr
Dented
Over 2 UpTo 10mm

No Image



17: Door osr
Scratched
Over 25mm Not Thru Paint

18: Door osf
Chipped
1 To 5



19: Wing osf
Poor Previous Repair
Poor Paint



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		