



VEHICLE INSPECTION REPORT

GX62LYR

Volvo XC60 D4 [163] SE Lux Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	03/12/2012	Body Style	Estate	Last service miles	101,014
Year	2012	Keys	2	MOT Due	25/02/2027
Mileage	151,906 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	11		
VIN	YV1DZ88A1D2401993	Last service date	23/09/2022		

last service 23/9/22 @ 101,014 miles (11 services 5 main dealer) Service due message displayed
 Reverse camera faulty

Tyres

NSF	HANKOOK	1.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	2.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Navigation system
- Service indicator
- Body coloured bumpers
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Seat Back Cover osr
Scuffed
Over 25mm



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wing nsf
Dented
Over 30mm



6: Wheel nsf
Scratched
Over 50mm



7: Flasher Side Repeater ns
Broken
Replace



8: Door nsf
Chipped
Edge Chip



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Bumper Rear
Chipped
1 To 5



13: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: Qtr Panel osr
Chipped
1 To 5



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Scratched
Over 25mm Thru Paint



18: Door osf
Chipped
Edge Chip



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm



21: Roof
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK