



VEHICLE INSPECTION REPORT

RJ13KKA

Volkswagen Touran 1.6 TDI 105 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	27/06/2013	Body Style	MPV	Last service miles	101,739
Year	2013	Keys	2	MOT Due	17/11/2026
Mileage	144,413 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	11		
VIN	WVGZZZ1TZDW075311	Last service date	27/07/2023		

Last Service - 27.07.2023 at 101739 miles (11 services) Service due message displayed
 Dpf warning light is on
 Intermittent over heating warning light

Tyres


NSF	BUDGET	5.0mm
NSR	FULDA	5.0mm
OSF	BUDGET	5.0mm
OSR	FULDA	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Steering wheel mounted controls
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm



3: Bumper Front Grill
Broken
Replace



4: Fog Lamp Surround ns
Missing
Replace



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Dented
Between 10mm + 30mm



9: Wheel nsr
Scratched
Over 50mm



10: Lamp nsr
Broken
Replace



11: Bumper Rear
Dented
With Paint Damage



12: Tailgate
Scratched
Up To 25mm Thru Paint



13: Wheel osr
Corroded
Light



14: Door osr
Chipped
1 To 5



15: Door osr
Dented
2 Or Less UpTo 10mm



16: Door osf
Dented
Over 30mm



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Chipped
1 To 5



19: Wing osf
Dented
2 Or Less UpTo 10mm



20: Fascia Trim
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK