



# VEHICLE INSPECTION REPORT

**LO11UPK**

## Nissan Qashqai 2.0 Tekna 5dr 4WD CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	30/06/2011	Keys	2	CAP Clean	£1,950.00
Year	2011	Service history	Yes	CAP Average	£1,525.00
Mileage	150,740 Miles Warranted	Service documents	Service Book	CAP Below	£1,100.00
Fuel Type	Petrol	Number of stamps	13	Gearbox	CVT
Colour	BEIGE	Last service date	09/10/2024	Gears	1
VIN	SJNFBNJ10U2306828	Last service miles	145,935	Doors	5
Body Style	Hatchback	MOT Due	26/10/2025		

Last Service: 09/10/2024 at 145935 miles. (13 services (1 main dealer) ) Noisy wheel bearing  
Car shakes and snakes across the road

### Tyres

NSF	MAXTREK	4.0mm
NSR	MAXTREK	4.0mm
OSF	MAXTREK	3.0mm
OSR	NANKANG	3.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Cruise control
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Central locking
- Navigation system
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Park assist camera
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Corroded  
Light



2: Wing osf  
Poor Previous Repair  
Poor Paint



3: Door Mirror Assy osf  
Broken  
Replace



4: Door osf  
Scratched  
Over 25mm Thru Paint



5: Door osr  
Scratched  
Over 25mm Thru Paint



6: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



7: Wheel osr  
Corroded  
Light



8: Bumper Rear  
Poor Previous Repair  
Paint Flake



9: Tailgate  
Chipped  
1 To 5



10: Wheel nsr  
Corroded  
Light



11: Door nsr  
Scratched  
Over 25mm Not Thru Paint



12: Door nsf  
Dented  
Over 30mm



13: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



14: Wheel nsf  
Corroded  
Light



15: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



16: Bumper Front  
Scratched  
Over 100mm Thru Paint



17: Bonnet  
Scratched  
Over 25mm Thru Paint



18: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



19: A Post os  
Dented  
With Paint Damage

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		