



VEHICLE INSPECTION REPORT

GX68VRD

Mitsubishi Eclipse Cross 1.5 2 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	26/09/2018	Body Style	Hatchback	Last service miles	72,640
Year	2018	Keys	2	MOT Due	25/09/2026
Mileage	80,021 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	6	Doors	5
VIN	JMAXJGK1WJZ000460	Last service date	13/09/2025		

£100 ADDITIONAL FEE

LAST SERVICE 13/09/2025 @ 72,640 MILES (6 SERVICES, 4 MAIN DEALER - BOOK & PRINT)
 CLUTCH REPLACED 16/04/2026.

Tyres

NSF	MAXTREK	4.0mm
NSR	MAXTREK	6.0mm
OSF	MAXTREK	4.0mm
OSR	MAXTREK	6.0mm

Spare

Features


- Bluetooth connection
- Rear wiper
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Park assist camera
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Door osf
Chipped
Edge Chip



3: Door osr
Dented
With Paint Damage



4: Qtr Panel osr
Dented
Between 10mm + 30mm



5: Bumper Rear
Scratched
25 to 100mm Thru Paint



6: Door nsr
Chipped
Edge Chip



7: Door nsr
Chipped
1 To 5



8: Door nsf
Chipped
Edge Chip



9: Door nsf
Dented
Between 10mm + 30mm



10: Wheel nsf
Scratched
Over 50mm



11: Bonnet
Dented
Over 30mm



12: Bumper Front
Scratched
25 to 100mm Thru Paint



13: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



14: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK