



VEHICLE INSPECTION REPORT

VK12JKU

Hyundai I40 1.6 GDi [135] Blue Drive Active 5dr



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	16/03/2012	Body Style	Estate	Last service miles	105,048
Year	2012	Keys	2	MOT Due	14/08/2026
Mileage	137,329 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	8		
VIN	KMHLB81ALCU009343	Last service date	27/07/2022		

last service 27/7/22 @ 105,048 miles (8 services 3 main dealer) book & print
 clutch replaced on 25/6/21 @ 93,053 miles Steering knocking
 Eml light is on
 Car been plugged in and detected
 Catalyst system efficiency below threshold (bank 1)
 Low clutch

Tyres




NSF	MICHELIN	3.0mm
NSR	BUDGET	5.0mm
OSF	MICHELIN	3.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- PAS
- Radio/CD
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Door nsr
Dented
Between 10mm + 30mm



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Dented
With Paint Damage



11: Tailgate
Scratched
Over 25mm Thru Paint



12: Qtr Panel osr
Dented
Between 10mm + 30mm



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Scratched
Over 25mm Thru Paint



16: Sill Panel Trim ns
Scratched (Painted)
Over 25mm Thru Paint



17: Door osf
Scratched
Over 25mm Thru Paint



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Roof
Rusted
Over 5mm



21: Bumper Front Grill
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	Fault