



# VEHICLE INSPECTION REPORT

**SN69HKC**

## Volvo V90 2.0 D4 R DESIGN 5dr Geartronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	31/10/2019	Body Style	Estate	Last service miles	73,346
Year	2019	Keys	1	MOT Due	12/05/2027
Mileage	73,860 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	8
Colour	WHITE	Number of stamps	5		
VIN	YV1PWA8UDK1108159	Last service date	01/05/2026		

Last service 01/05/2026 at 73,346 miles- 5 services (3 main dealer)  
 MOT in 2024 recorded in KM on MOT history

### Tyres



NSF	BRIDGESTONE	4.0mm
NSR	YOKOHAMA	5.0mm
OSF	BRIDGESTONE	4.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Partial leather seat trim

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Dented  
With Paint Damage



3: Wheel nsf  
Scratched  
Over 50mm



4: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



5: Door nsf  
Dented  
Between 10mm + 30mm



6: Door nsf  
Chipped  
Edge Chip



7: Sill ns  
Scratched  
UpTo 25mm Thru Paint



8: Door nsr  
Chipped  
1 To 5



9: Wheel nsr  
Scratched  
Over 50mm



10: Bumper Rear  
Dented  
With Paint Damage



11: Wheel osr  
Scratched  
Over 50mm



12: Door osr  
Chipped  
1 To 5




13: Door osf  
Chipped  
1 To 5



14: Wheel osf  
Scratched  
Over 50mm



15: A Post ns  
Chipped  
1 To 5



16: Screen Front  
Chipped  
UpTo 10mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK