



VEHICLE INSPECTION REPORT

WO15XGP

Jeep Renegade 1.4 Multiair Longitude 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/07/2015	Body Style	Estate	Last service miles	101,134
Year	2015	Keys	2	MOT Due	Expired
Mileage	101,680 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	7		
VIN	1C4BU0000FPC12313	Last service date	28/04/2026		

Last service 28/04/2026 at 101,134 miles- 7 services

MOT EXPIRED Eml light is on

Car been plugged in and detected

computer has intentionally turned off the fuel supply to a cylinder because of repeated, severe misfires

Tyres


NSF	BUDGET	6.0mm
NSR	MICHELIN	5.0mm
OSF	BUDGET	6.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
UpTo 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



6: Flasher Side Repeater ns
Broken
Replace



7: Door nsf
Chipped
1 To 5



8: Door nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Up To 50mm



10: Qtr Panel nsr
Dented
Over 30mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint




12: Qtr Panel osr
Dented
Over 30mm



13: Qtr Panel osr
Chipped
1 To 5



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Chipped
Edge Chip




17: Handle Outer osf
Scratched (Painted)
UpTo 25mm Thru Paint



18: Wheel osf
Scratched
Up To 50mm



19: Wing osf
Chipped
1 To 5



20: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK