



VEHICLE INSPECTION REPORT

SY68VKX

Hyundai Tucson 1.6 CRDi 136 Premium SE 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	31/10/2018	Body Style	Estate	Last service miles	47,994
Year	2018	Keys	1	MOT Due	03/11/2026
Mileage	49,564 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	7		
VIN	TMAJ3817LKJ731286	Last service date	05/11/2025		

Last service 05/11/2025 at 47,994 miles- 7 services (6 main dealer) intermitted engine tapping

Tyres

NSF	TOMKET	2.0mm
NSR	KUMHO	3.0mm
OSF	TOMKET	2.0mm
OSR	KUMHO	3.0mm

Spare

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Alarm
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front armrest
- Lumbar support
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Front parking sensor
- PAS
- Trip computer
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Radio/CD
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Door osf
Chipped
Edge Chip



10: Door osf
Scratched
Over 25mm Thru Paint



11: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		