



VEHICLE INSPECTION REPORT

KN65LVA

Volkswagen Tiguan 2.0 TDi BlueMotion Tech R-Line 184 5dr DSG [NAV]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	16/10/2015	Body Style	Estate	Last service miles	113,118
Year	2015	Keys	2	MOT Due	10/09/2026
Mileage	121,050 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Service Book	Gears	7
Colour	BLACK	Number of stamps	8		
VIN	WVGZZZ5NZGW034250	Last service date	03/09/2025		

£90 ADDITIONAL FEE

Last Service - 03.09.2025 at 113118 miles (8 services)

Touch screen on radio does not work

EML light is on car has been plugged in and detects cylinder 4 glow plug circuit

Ignition distributor engine speed input system voltage to low

Tyres

NSF	LAUFENN	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Up To 50mm



2: Wing of
Chipped
1 To 5



3: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



4: Door osf
Dented
With Paint Damage



5: Door osr
Dented
Between 10mm + 30mm



6: Door osr
Chipped
1 To 5



7: Bumper Rear
Dented
With Paint Damage



8: Tailgate
Chipped
Multiple Chips



9: Wheel nsr
Scratched
Over 50mm



10: Door nsr
Chipped
1 To 5



11: Door Moulding nsr
Scratched (Painted)
Over 25mm Thru Paint



12: Door nsf
Dented
With Paint Damage



13: Wing nsf
Dented
Between 10mm + 30mm



14: Wheel nsf
Scratched
Over 50mm



15: Bumper Front
Chipped
Multiple Chips



16: Bonnet
Chipped
1 To 5



17: Screen Front
Chipped
Up To 10mm



18: Roof
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	Fault
Sat nav	OK	Steering	OK